FAIRFIELD TOWNSHIP RESOLUTION NO. 20-86

RESOLUTION TO APPROVE REPAIR OF FIRE ENGINE #211 FROM SPECIALTY TRUCK REPAIR INC., AT A TOTAL COST OF \$7,500.00.

WHEREAS: Fire Engine #211 needs repairs in order to be fully operational; and WHEREAS: The repairs will be purchased from Specialty Truck Repair, Inc., out of Fund No. 2111; NOW, THEREFORE, BE IT RESOLVED, by the Board of Trustees of Fairfield Township, Butler County, Ohio, as follows; **SECTION 1:** The Board hereby approves the repair of Fire Engine #211, Specialty Truck Repair, Inc., at a total cost of \$7,500.00, as set forth on attached Exhibit "A". **SECTION 2:** The Board hereby dispenses with the requirement that this resolution be read on two separate days, pursuant to RC 504.10, and authorizes the adoption of this resolution upon its first reading. **SECTION 3:** This resolution is the subject of the general authority granted to the Board of Trustees through the Ohio Revised Code and not the specific authority granted to the Board of Trustees through the status as a Limited Home Rule Township. SECTION 4: That it is hereby found and determined that all formal actions of this Board concerning and relating to the passage of this Resolution were taken in meetings open to the public, in compliance with all legal requirements including §121.22 of the Ohio Revised Code. **SECTION 5:** This resolution shall take effect at the earliest period allowed by law. **Adopted:** May 27, 2020 **Board of Trustees Vote of Trustees** Shannon Hartkemeyers Susan Berding: **AUTHENTICATION** This is to certify that this is a resolution which was duly passed, and filed with the Fairfield Township Fiscal Officer this 27th day of 1 2020. ATTEST: Shelly Schultz, Fairfield Township Fiscal Officer

APPROVED AS TO FORM:

awrence É. Barbiere, Township Law Director

Specialty Truck Repair, Inc.

90 Jolly Industrial Park Dr. Wilder, KY 41076-9773 Phone 859-442-5100 Fax 859-442-7048

Estimate

DATE	ESTIMATE#
5/16/2020	1432

NAME / ADDRESS
Fairfield Township Fire Dept. 6048 Morris Road Fairfield Twp., OH. 45011

Unit no.		
	E211 019	

\$7,500.00

QTY	DESCRIPTION	cost	TOTAL
	Check steering, steering wanders. Align front axle and reset caster	600.00	600.00
	Check drive axle. Suspension components worn. Suspension obsoleted by Hendrickson in 2010. Replace existing suspension components with updated suspension and align rear axle.	6,900.00	6,900.00
	5-7 day lead time on Hendrickson parts.		

TOTAL

Estimate good for 30 days