

**FAIRFIELD TOWNSHIP  
RESOLUTION NO. 24-122**

**RESOLUTION APPROVING REPAIR OF FIRE ENGINE #213, FROM SPECIALTY TRUCK  
REPAIR, INC., AT A TOTAL COST OF \$30,901.41.**

**WHEREAS:** Fire Engine #213 needs head gasket and subframe crack repairs in order to be fully operational;

**NOW, THEREFORE, BE IT RESOLVED,** by the Board of Trustees of Fairfield Township, Butler County, Ohio, as follows;

**SECTION 1:** The Board hereby approves the truck repair for Fire Engine #213, from Specialty Truck Repair, Inc., at a total cost of \$30,901.41, as set forth on attached Exhibit "A".

**SECTION 2:** The Board hereby dispenses with the requirement that this resolution be read on two separate days, pursuant to RC 504.10, and authorizes the adoption of this resolution upon its first reading.

**SECTION 3** This resolution is the subject of the general authority granted to the Board of Trustees through the Ohio Revised Code and not the specific authority granted to the Board of Trustees through the status as a Limited Home Rule Township.

**SECTION 4:** That it is hereby found and determined that all formal actions of this Board concerning and relating to the passage of this Resolution were taken in meetings open to the public, in compliance with all legal requirements including §121.22 of the Ohio Revised Code.

**SECTION 5:** This resolution shall take effect at the earliest period allowed by law.

**Adopted:** August 13, 2024

**Board of Trustees**

Shannon Hartkemeyer: \_\_\_\_\_

Michael Berding: \_\_\_\_\_

Joe McAbee: \_\_\_\_\_

**Vote of Trustees**

yes

yes

yes

**AUTHENTICATION**

This is to certify that this is a resolution which was duly passed and filed with the Fairfield Township Fiscal Officer this 13th day of August, 2024.

**ATTEST:**

Shelly Schultz

Shelly Schultz, Fairfield Township Fiscal Officer

**APPROVED AS TO FORM:**

Lawrence E. Barbieri

Lawrence E. Barbieri, Township Assistant Law Director

# Specialty Truck Sales &

Fax 859-442-7048  
 90 Jolly Industrial Park Dr.  
 Wilder, KY 41076-9773

# Estimate

DATE	ESTIMATE #
7/31/2024	1670

NAME / ADDRESS
Fairfield Township Fire Dept. 6048 Morris Road Fairfield Twp., OH. 45011

Unit no.
027

QTY	DESCRIPTION	COST	TOTAL
6	C PM service	150.00	900.00
1	Replace transmission filter	150.00	150.00
0.5	Clean and treat air filter	150.00	75.00
1	Service generator	150.00	150.00
1	BALBF1378-SPS filter	66.96	66.96
1	BALBF7924 filter	37.77	37.77
1	BALBW5071 filter	22.36	22.36
1	BALPT9415MPG filter	155.97	155.97
1	BALBD7309 filter	78.72	78.72
1	FLECV50628 filter	272.25	272.25
1	BALBT839-10 filter	14.44	14.44
20	MIS15w40 oil	6.32	126.40
4	MISSYNATF synthetic ATF	19.72	78.88
1	99-5000 KN air filter cleaning kit	42.82	42.82
1.5	Rebuild and install intake relief valve	150.00	225.00
1	HAL546-00031-00-0 intake relief valve kit	385.69	385.69
2	Replace pump transmission output shaft seal	150.00	300.00
<b>TOTAL</b>			

# Specialty Truck Sales &

Fax 859-442-7048  
 90 Jolly Industrial Park Dr.  
 Wilder, KY 41076-9773

# Estimate

DATE	ESTIMATE #
7/31/2024	1670

NAME / ADDRESS
Fairfield Township Fire Dept. 6048 Morris Road Fairfield Twp., OH. 45011

		Unit no.	
		027	
QTY	DESCRIPTION	COST	TOTAL
1	MERA105E1227 seal	33.46	33.46
1	HAL048-1580-50-0 G case bearing kit	141.00	141.00
13	MIS75w90 oil	9.41	122.33
36	Check coolant leak	150.00	5,400.00
	Found leaks from EGR cooler and head gasket. Replace ER cooler (upgrade EGR cooler) and head gasket. Remove radiator and charge air cooler to be cleaned and checked. Replace thermostat and flush cooling system		
	Post repair pump service test 1500 GPM and less (Per NFPA 1910)	300.00	300.00
	Clean and test radiator	175.00	175.00
	Clean and test charge air cooler	225.00	225.00
1	5473339 upper engine gasket set	418.98	418.98
6	3867471 o-ring	2.40	14.40
6	3937142 injector seal	4.05	24.30
6	4954487 o-ring	3.96	23.76
2	3627695 o-ring	9.73	19.46
2	3684202 connector	24.79	49.58
1	3678603 o-ring	4.98	4.98
<b>TOTAL</b>			

# Specialty Truck Sales &

Fax 859-442-7048  
 90 Jolly Industrial Park Dr.  
 Wilder, KY 41076-9773

# Estimate

DATE	ESTIMATE #
7/31/2024	1670

NAME / ADDRESS
Fairfield Township Fire Dept. 6048 Morris Road Fairfield Twp., OH. 45011

		Unit no.	
		027	
QTY	DESCRIPTION	COST	TOTAL
2	3922794 o-ring	3.86	7.72
1	3931284 o-ring	5.11	5.11
2	3957942 connector	19.30	38.60
1	3678912 o-ring	3.78	3.78
1	3678786 o-ring	4.20	4.20
2	4984382 sealing washer	10.88	21.76
8	3959799 isolator	9.53	76.24
4	3818824 nut	4.34	17.36
26	3960043 head bolt	11.17	290.42
12	3944593 bolt	5.23	62.76
1	3966768 harness	66.32	66.32
1	5255739 breather tube	108.78	108.78
1	5271480 o-ring	7.12	7.12
1	5273379 thermostat	75.98	75.98
1	4936967 seal	19.68	19.68
1	4352347 EGR cooler retrofit kit	989.18	989.18
1	4376312 EGR cooler	2,364.52	2,364.52
1	63-2469 coolant sensor	136.42	136.42
1	custom hose	125.00	125.00
<b>TOTAL</b>			

# Specialty Truck Sales &

Fax 859-442-7048  
 90 Jolly Industrial Park Dr.  
 Wilder, KY 41076-9773

# Estimate

DATE	ESTIMATE #
7/31/2024	1670

NAME / ADDRESS
Fairfield Township Fire Dept. 6048 Morris Road Fairfield Twp., OH. 45011

Unit no.
027

QTY	DESCRIPTION	COST	TOTAL
1	reconditioned cylinder head	4,200.00	4,200.00
15	gal MISFC50/50 coolant	39.73	595.95
	Misc parts and shop supplies	250.00	250.00
70	Firebody subframe cracked. Remove booster tank. Clean and repair subframe. Realign and weld crossmembers. Add and weld in additional support for subframe. Install booster tank.	150.00	10,500.00
2	3"x3"x.25"x60" aluminum tube	175.00	350.00
2	.75"x3"X60" aluminum flat bar	150.00	300.00
	Misc parts and shop supplies	250.00	250.00
<b>TOTAL</b>			<b>\$30,901.41</b>

Estimate good for 30 days