

FAIRFIELD TOWNSHIP
RESOLUTION NO. 17-120

**RESOLUTION TO AUTHORIZE REPAIRS FOR FIRE ENGINE 211 FROM BRIGHTON
SPRING SERVICE COMPANY, INC. IN THE AMOUNT NOT TO EXCEED \$4,500.00.**

WHEREAS: The Fire Chief has indicated that Fire Engine 211 is out of service until the repairs are made;

NOW, THEREFORE, BE IT RESOLVED, by the Board of Trustees of Fairfield Township, Butler County, Ohio, as follows;

SECTION 1: The Board hereby approves the repair work for Fire Engine 211 from Brighton Spring Service Company, Inc., 7975 North Gilmore Road, Fairfield, OH 45014, in the amount not to exceed \$4,500.00 as attached from "Exhibit A" from Fund No. 2111-220-323.

SECTION 2: The Board hereby dispenses with the requirement that this resolution be read on two separate days, pursuant to RC 504.10, and authorizes the adoption of this resolution upon its first reading.

SECTION 3: This resolution is the subject of the general authority granted to the Board of Trustees through the Ohio Revised Code and not the specific authority granted to the Board of Trustees through the status as a Limited Home Rule Township.

SECTION 4: That it is hereby found and determined that all formal actions of this Board concerning and relating to the passage of this Resolution were taken in meetings open to the public, in compliance with all legal requirements including §121.22 of the Ohio Revised Code.

SECTION 5: This resolution shall take effect at the earliest period allowed by law.

Adopted: November 15, 2017

Board of Trustees

Susan Berding:

Susan Berding

Shannon Hartkemeyer:

Shannon Hartkemeyer

Joe McAbee:

Joe McAbee

Vote of Trustees

yes

yes

yes

AUTHENTICATION

This is to certify that this is a resolution which was duly passed, and filed with the Fairfield Township Fiscal Officer this 15th day of Nov., 2017.

ATTEST:


Nancy A Bock

Nancy Bock, Fairfield Township Fiscal Officer

APPROVED AS TO FORM:

L. E. Barbieri

Lawrence E. Barbieri, Township Law Director



Brighton
Spring Service Co., Inc.

Suspension Parts & Service

7975 North Gilmore Road, Fairfield, OH 45014
 (513) 942-2960 • (513) 621-2960

ALIGNMENT SHOP
 (513) 870-6551

NORTH
 8550
 11/14/17

03:42P

FAIR FIRE
 FAIRFIELD TOWNSHIP FIRE
 6048 MORRIS ROAD
 HAMILTON OH 45011

ShipName : CHIEF THOMAS
 UNIT : 461-3777
 WorkOrder: # 211
 Telephone: (513) 887-4402x
 Fax: ()
 P/O# :

Reighen U-Bolts Within 10 Days

QTY	Part Number	Description	Cost	Extension
1	R201482	KING PIN SET	703.29	703.29
2	380048A	SEAL,	57.33	114.66
4	BU270	KP BUSHING	32.75	131.00
4	RI428	7/8 U-BOLT/ROD	24.96	99.84
1	MISC	C BOLT, PADS, CLIPS	13.36	13.36
16	BFT2200	3/4 X 2 BOLT	5.91	94.56
11	KPS	KING PIN SHIMS	1.65	18.15
1	KP	REMOVED AND REPLACED BOTH KING PINS	600.00	600.00
4	NSI-SS1	SUPPLIES	20.00	80.00

SIGNATURE

***** F I L E C O P Y *****

PARTS 1,254.86
 LABOR 600.00
 FREIGHT 0.00
 TAX 0.00
 TOTAL 1,854.86
 CHARGE

* This is a Quote * This is a Quote * This is a Quote * This is a Quote * This is a Quote *
 FINANCE CHARGE OF 18% ANNUAL CHARGED. CUSTOMER AGREES TO PAY ATTORNEYS FEES & COST FOR COLLECTION. WAIVAR
 (800) 762-7901 / www.brightonspring.com



Brighton
Spring Service Co., Inc.

Suspension Parts & Service

7975 North Gilmore Road, Fairfield, OH 45014
 (513) 942-2960 • (513) 621-2960

ALIGNMENT SHOP
 (513) 870-6551

NORTH
 8551
 11/14/17

03:42P

FAIR FIRE
 FAIRFIELD TOWNSHIP FIRE
 6048 MORRIS ROAD
 HAMILTON OH 45011

ShipName.: CHIEF THOMAS 461-3777
 UNIT.....: # 211
 WorkOrder:
 Telephone: (513) 887-4402x
 Fax.....: ()
 P/O#.....: ~~887-~~ 2705

Reignite U-Bolts Within 10 Days


QTY	Part Number	Description	Cost	Extension
1	ES3030R	TIR ROD END--	164.51	164.51
1	ES3031L	TIR ROD END--	164.50	164.50
1	464.206	CROSS TUBE	241.36	241.36
2	NSI-CLAMPS	CLAMP	24.50	49.00
2	FB12300	3/4 X 3 FLANGE BOLT	15.42	30.84
1	BTRR	REMOVED AND REPLACED BOTH TIR ROD ENDS AND INSTALLED ON VEHICLE SUPPLIES	90.00	90.00
1	NSI-SS1		20.00	20.00

SIGNATURE

***** F I L E C O P Y *****

PARTS 670.21
 LABOR 90.00
 FREIGHT 0.00
 TAX 0.00
****TOTAL** 760.21**
 CHARGE

* This is a Quote * This is a Quote * This is a Quote * This is a Quote * This is a Quote * This is a Quote *
 FINANCE CHARGE OF 18% ANNUM CHARGED. CUSTOMER AGREES TO PAY AUTOBILTY'S FEES & COST FOR COLLECTION. WARVAR.



Brighton
Spring Service Co., Inc.

Suspension Parts & Service

7975 North Gilmore Road, Fairfield, OH 45014
 (513) 942-2960 • (513) 621-2960

ALIGNMENT SHOP
 (513) 878-6551

NORTH
 8552
 11/14/17

03:42P

FAIR FIRE
 FAIRFIELD TOWNSHIP FIRE
 6048 MORRIS ROAD
 HAMILTON OH 45011

ShipName.: CHIEF THOMAS 461-3777
 UNIT..... # 211
 WorkOrder:
 Telephone: (513) 887-4402x
 Fax..... ()
 P/O#.....

Retighten U-Bolts Within 10 Days

QTY	Part Number	Description	Cost	Extension
2	RB299	BUSHING--56648-000	53.75	107.50
2	MHS91	HENDRICKSON CONCENTRIC COLLAR	27.00	54.00
2	MHS93	HENDRICKSON ECCENTRIC COLLAR	27.00	54.00
2	MHS9110	AIR SPRING BRACKET	19.60	39.20
2	BF16750	1 X 7 1/2 BOLT	26.16	52.32
2	321-388	BUSHING "D" PIN	127.50	255.00
4	BF16600	1 X 6 BOLT	18.80	75.20
1	LABOR	REBUSH REAR FIRE-MAXX BEAM	450.00	450.00
1	A2	TWO AXLE ALIGNMENT	200.00	200.00
5	NSI-SS1	SUPPLIES	20.00	100.00

SIGNATURE

***** R I L E C O P Y *****

PARTS 737.22
 LABOR 450.00
 FREIGHT 0.00
 TAX 0.00
 TOTAL 1,387.22
 CHARGE

* This is a Quote * This is a Quote * This is a Quote * This is a Quote * This is a Quote *
 FINANCE CHARGE OF 18% ANNUUM CHARGED. CUSTOMER AGREES TO PAY ATTORNEYS FEES & COST FOR COLLECTION, WARWAR.
 (800) 752-7901 / www.brightonspring.com