



Monthly Activity Report

July 2025

Answered phone calls from residents and dealt with them accordingly.

Made sure park trash was emptied, and parks are in working order.

Monthly playground and storm water inspections.

Cleaned shop area along with offices and break area.

Cold patch any necessary holes within the township.

Drag ball fields weather permitting.

Mow grass on township properties.

Remove the remaining trees on Hickory Trail to prevent further damage to the sump line collector.

Repair sump line collection line at 6027 Indian Trace.

Install for sale sign on township property with new contact number.

Install AEDs at township parks per request.

Repair sum line collection line at 6425 Taylor Trace Ln.

Clear fallen tree free from road at 3371 Spring Crest Dr.

Locate several catch basin failures and mark for repair

Repair catch basin at 3963 Hickory Trail.

Pull at spray weeds at Milton Pocket Park.

Repair catch basin at 6140 Lovelace Dr.

Repair catch basin at corner of Creekside Dr. and Lovelace Dr.