

FAIRFIELD TOWNSHIP
RESOLUTION NO. 19-90

**RESOLUTION TO APPROVE REPAIR OF FIRE ENGINE #213 FROM SPECIALTY TRUCK
REPAIR INC., AT A TOTAL COST OF \$5,102.32.**

WHEREAS: Fire Engine #211 is in need of repairs in order to be fully operational; and

WHEREAS: The repairs will be purchased from Specialty Truck Repair, Inc., out of Fund No. 2111;

NOW, THEREFORE, BE IT RESOLVED, by the Board of Trustees of Fairfield Township, Butler County, Ohio, as follows;

SECTION 1: The Board hereby approves the repair of Fire Engine #213, from Specialty Truck Repair, Inc., at a total cost of \$5,102.32, as set forth on attached Exhibit "A".

SECTION 2: The Board hereby dispenses with the requirement that this resolution be read on two separate days, pursuant to RC 504.10, and authorizes the adoption of this resolution upon its first reading.

SECTION 3 This resolution is the subject of the general authority granted to the Board of Trustees through the Ohio Revised Code and not the specific authority granted to the Board of Trustees through the status as a Limited Home Rule Township.

SECTION 4: That it is hereby found and determined that all formal actions of this Board concerning and relating to the passage of this Resolution were taken in meetings open to the public, in compliance with all legal requirements including §121.22 of the Ohio Revised Code.

SECTION 5: This resolution shall take effect at the earliest period allowed by law.

Adopted: July 10, 2019

Board of Trustees


Vote of Trustees

Shannon Hartkemeyer: 

yes

Joe McAbee: 

yes

Susan Berding 

yes


AUTHENTICATION

This is to certify that this is a resolution which was duly passed, and filed with the Fairfield Township Fiscal Officer this 10th day of July, 2019.

ATTEST:


Shelly Schultz, Fairfield Township Fiscal Officer

APPROVED AS TO FORM:


Lawrence E. Barbieri, Township Law Director

Specialty Truck Repair, Inc.

6 Beacon Drive
 Wilder, KY 41076-9773
 Phone 859-442-5100
 Fax 859-442-7048

Estimate

DATE	ESTIMATE #
7/7/2019	1364

NAME / ADDRESS
Fairfield Township Fire Dept. 6048 Morris Road Fairfield Twp., OH. 45011

		Unit no.	
		E213 008	
QTY	DESCRIPTION	COST	TOTAL
	This estimate is for needed repairs found during the PM service		
12	Replace tank fill piping from booster tank to tank fill valve	105.00	1,260.00
	Rebuild tank fill valve		
	Lubricate right jump seat window linkages and operator		
	Adjust pump packing		
	Found air leak at foot valve with service brakes applied.		
	Replace leaking brake light switch.		
	Replace tie rod ends	187.50	187.50
	Align front axle	125.00	125.00
	Replace both front springs	575.00	575.00
1	K101977 switch	92.70	92.70
1	1.5x90SS elbow	33.54	33.54
1	1.5x5SS nipple	27.00	27.00
1	1.5MPx1.5JIC fitting	41.30	41.30
1	custom hose	105.00	105.00
1	ELK891 valve kit	86.40	86.40
1	WS2090L tie rod end	81.25	81.25
1	2091R tie rod end	81.25	81.25
TOTAL			

Specialty Truck Repair, Inc.

6 Beacon Drive
 Wilder, KY 41076-9773
 Phone 859-442-5100
 Fax 859-442-7048

Estimate

DATE	ESTIMATE #
7/7/2019	1364

NAME / ADDRESS
Fairfield Township Fire Dept. 6048 Morris Road Fairfield Twp., OH. 45011

Unit no.
E213 008

QTY	DESCRIPTION	COST	TOTAL
2	41302 spring	950.00	1,900.00
2	B11469-43 spring pin	54.95	109.90
2	FS955 shackle kit	134.34	268.68
4	R1224 u-bolt	19.60	78.40
6	BF10200 5/8x2 bolt	4.90	29.40
	shop supplies	20.00	20.00
TOTAL			\$5,102.32

Estimate good for 30 days